


FIG. 2






FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E




FIG. 3F




FIG. 3G






FIG. 3H





 $(Y-AXIS SENSITIVITY) = (X-AXIS SENSITIVITY) \times Sin \theta 1$ 

